ECS/EMD Configuration Change Request					Page 1 of Page(s)			je(s)
1. Originator	2. Log Date:	3. CCR #:		4. Rev:	5. Tel:	(6. Rm #:	7. Org.
Benzell Floyd	12/15/03	03-0825		_	(301)925-0518	(3083	COTS SW
8. CCR Title: Release Remedy ILM, PuTTY 0.5b, and WinZip 8.1 software to the DAACs								
9. Originator Signature/Date			10. CI	lass 11. Type: 12. Need Date: 12/16/03			: 12/16/03	
Benzell Floyd /s/ 12/15/03			II		CCR			
13. CCR Sponsor Signature/Date			14. Category of				"Emergency"	
Pamela Johnson /s/ 12/15/03			PSR	Routine				
• ,				Schedule 18. CI(s) Affected:MLCI, MCI act:				
19. Release Affected by this Change: 20. Date due			to Customer: 21. Estimated Cost:					
6B 12/16/			None - Under 100K					
22. Source Reference: NCR (attach) Action Item Tech Ref. GSFC Other: NCRs are listed on the Additional Sheet. Other: Ticket #: KS_XT_02 (XRP Conversion to Remedy ILM).								
23. Problem: (use additional Sheets if necessary) The XRP ILM software (used to keep track of ECS hardware inventory items and COTS software licenses) has reached its end of life and is not economically supportable on ECS baselined computers. The XRP ILM software needs to be replaced.								
24. Proposed Solution: (use additional sheets if necessary) Replace XRP ILM software with Remedy ILM software, ILM scripts, and COTS: PuTTY 0.53b and WinZip 8.1. Deliver the files, RemedyILMcomponents.tar.gz and PuTTY_053b.zip and the WinZip 8.1 CD to the DAACs. Install Remedy ILM, PuTTY version 0.53b, and WinZip 8.1 software in accordance with instructions in the PSR document, 914-TDA-264. Tar file information: Filename: RemedyILMcomponents.tar.gz, Checksum: 1289171430, Size: 41483379, Filename: PuTTY_0.53b.zip, Checksum: 249476049, Size: 979367								
25. Alternate Solution: (use additional sheets if necessary) None								
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) ILM software capabilities will not be available on ECS baselined hosts and therefore not available for use by the ECS ILS staff.								
27. Justification for Emergency (If Block 15 is "Emergency"):								
28. Site(s) Affected: ⊠EDF ⊠PVC ⊠VATC ⊠EDC ⊠ GSFC ⊠LaRC ⊠NSIDC □SMC □AK □JPL □EOC □ IDG Test Cell □Other								
29. Board Comments:				30. \	Work Assigned T	o: S	31. CCR C	closed Date:
32. SCDV CCB Chair (Sign		Disposition: Ar	oproved	App/C	om. Disapproved	l With	hdraw Fw	d/ESDIS ERB
Byron V. Peters /s/ 1	2/16/03	<u> </u>	vd/ECS					
33. EDF CCB Chair (Sign/D	ate):	Disposition: Ap		App/Co	m. Disapproved	l With	hdraw Fwd	I/ESDIS ERB
34. ECS CCB Chair (Sign/D	late):			Ann/Co	m Disannroved	\/\/i+k	hdraw Fw	d/ESDIS ERR
The Local Control (Cigilla)	,.	•	pproved App/Com. Disapproved Withdraw Fwd/ESDIS ERB wd/ESDIS					

CM01JA00 Revised 10/2/03 ECS/EDF/SCDV

ADDITIONAL SHEET

CCR #: 03-0825 Rev: — Originator: Benzell Floyd

Telephone: (301) 924-0518 Office: 3083

Title of Change: Release Remedy ILM, PuTTY 0.5b, and WinZip 8.1 software to the DAACs

Reference 16. (Documents/Drawings Impacted

910-TDA-003 910-TDA-023 920-TDE-002 920-TDG-002 920-TDL-002

920-TDN-002

920-TDS-002 920-TDP-002

920-TDV-002

Reference 22: (Source Reference: NCRs)

ECSed15131, "Where command not restoring data entry screen on exit (XRP-II)" ECSed27170, "XRP-II: Installation processing"

ECSed27174, "XRP-II: EIN Relocation trx can update records incorrectly" ECSed27187, "XRP-II: Adding/deleting records can affect other users' screens"

ECSed29253, "XRP-II: Occasionally fails on startup on Sparc 20s"

CM01AJA00 Revised 10/2/03 ECS/EMD